

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: Fire Prevention-Follow-up

DATE OCCURRED 03-17-98

DATE REPORTED

TIME OCCURRED

TIME REPORTED

LOCATION(S) OF OCCURRENCE:

Aero Flight 8555 Perimeter Rd

REPORTED BY:

PHONE NO(S):

Cpl Dickie

SUMMARY:

Ref: Officer Report dated 03-14-98 by Legg/Proffitt: I made contact with Aero Flight owner: Mike Hill and Fuel Line Manager: Marc Blume; and Maintenance Manager: Eric Wheaton. We discussed the need for immediate corrective action on the 03-14 incident. The main areas of concern were the 1. the improper clean-up procedures used during flammable liquids spills; and 2. failure to have on hand proper fuel spill clean-up materials, as outlined in the letter (from Don Smith, dated: May 22, 1992) to all fuel dealers. All parties agreed to immediate corrective action. I provided a copy of the report and the 05-22-92 letter to the Aero Flight people. I will be doing follow-up inspections over the next week and will provide an inspection report.

OFFICERS:

ACTION:

KCSlip4 52727

SEA419087